



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D5650-041
Job Sheet 198564



Part No: D5650-041

Job Qty: 200 pcs

Part Name: Bushing Assembly



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 7/31/19

Job Tracking No:

Due Date: 8/30/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: D5650 REV.B IPP REV:A 18.05.28 NEW ISSUE DD VERF:JFS IPP REV.B 18.07.19 AS PER DWG REV.A DD
VERF:JFS IPP REV:C 19.07.23 AS PER DWG REV.B DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Hardinge - 1	200 pcs	8/30/19	8/30/19	0.50	9.09	Hardinge - 1		BT 19/08/21
115	QC 2	200 pcs	8/30/19	8/30/19	0.00	0.00	QC 2 - 1		
							QC 2 - 12		
							QC 2 - 14		
							QC 2 - 17		
							QC 2 - 19		
							QC 2 - 2		
							QC 2 - 20		
							QC 2 - 22		
							QC 2 - 23		
							QC 2 - 25		
							QC 2 - 32		
							QC 2 - 33		
							QC 2 - 35		
							QC 2 - 39		
							QC 2 - 4		
							QC 2 - 40		
							QC 2 - 44		
							QC 2 - 45		
							QC 2 - 48		
							QC 2 - 49		
							QC 2 - 50		
							QC 2 - 51		
							QC 2 - 52		
							QC 2 - 57		
							QC 2 - 62		
							QC 2 - 63		
							QC 2 - 8		
							QC 2 - 66		
							QC 2 - 64		



Container No: S207575



Part: D5650 - 041

Job No: 198564

Serial No/Batch: S207575

Revision: B

Inspector:

Exp Date:

Instructions: Various STC's

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Date: 08/21/19

120	QC 8	200 pcs	8/30/19	0.00 0.00	QC 2 - 65	
					QC 2 - 5	
					QC 2 - 71	
					QC 2 - 73	
					QC 2 - 69	
					QC 8 - 12	
					QC 8 - 14	
					QC 8 - 17	
					QC 8 - 20	
					QC 8 - 25	
					QC 8 - 3	
					QC 8 - 32	
					QC 8 - 33	
					QC 8 - 35	
					QC 8 - 39	
					QC 8 - 4	
					QC 8 - 44	
					QC 8 - 45	
					QC 8 - 49	
					QC 8 - 58	
					QC 8 - 8	
					QC 8 - 9	
					QC 8 - 68	
					QC 8 - 67	
					QC 8 - 1 (A)	
					QC 8 - 47	
					QC 8 - 40	
					QC 8 - 52	
					QC 8 - 23	
					QC 8 - 57	
130	Small Fab - 2 - B4B	200 pcs	8/30/19	0.00 9.09	Small Fab - 1 - B4B	
					Small Fab - 2 - B4B	
					Small Fab - 3 - B4B	
					Small Fab - 4 - B4B	
					Small Fab - 5 - B4B	
					Small Fab - 6 - B4B	
					Small Fab - 7 - B4B	
					Small Fab - 8 - B4B	
140	QC 5	200 pcs	8/30/19	0.00 0.00	QC 5 - 10	
					QC 5 - 12	
					QC 5 - 17	
					QC 5 - 18	
					QC 5 - 19	
					QC 5 - 22	
					QC 5 - 24	
					QC 5 - 3	
					QC 5 - 43	
					QC 5 - 49	
					QC 5 - 51	
					QC 5 - 58	
					QC 5 - 68	
					QC 5 - 9	
					QC 5 - 50	
					QC 5 - 30	
					QC 5 - 40	
					QC 5 - 61	
					QC 5 - 81	
150	Packaging 3-1 - Stock - B4B	200 pcs	8/30/19	0.00 0.00	Packaging 3 - 1 - B4B	
					Packaging 3 - 2 - B4B	

JBD 14/08/21

JBD 14/08/21

AUG 21 2019

DAS
81
9-89

AUG 21 2019

Wed 8-21-2019
Oscar

Packaging 3 - 3 - B4B	ST180
Packaging 3 - 4 - B4B	
Packaging 3 - 5 - B4B	
Packaging 3 - 6 - B4B	
Packaging 3 - 7 - B4B	
Packaging 3 - 8 - B4B	
Packaging 3 - 9 - B4B	
Packaging 3 - 10 - B4B	
Packaging 3 - 11 - B4B	
Packaging 3 - 12 - B4B	
Packaging 3 - 13 - B4B	
Packaging 3 - 14 - B4B	
Packaging 3 - 15 - B4B	
Packaging 3 - 16 - B4B	
Packaging 3 - 17 - B4B	
Packaging 3 - 18 - B4B	
Packaging 3 - 19 - B4B	
Packaging 3 - 20 - B4B	
Packaging 3 - 21 - B4B	
Packaging 3 - 22 - B4B	
Packaging 3 - 23 - B4B	
Packaging 3 - 24 - B4B	
Packaging 3 - 25 - B4B	
Packaging 3 - 26 - B4B	
Packaging 3 - 27 - B4B	
Packaging 3 - 28 - B4B	
Packaging 3 - 29 - B4B	
Packaging 3 - 30 - B4B	
Packaging 3 - 31 - B4B	
Packaging 3 - 32 - B4B	
Packaging 3 - 33 - B4B	
Packaging 3 - 34 - B4B	
Packaging 3 - 35 - B4B	
Packaging 3 - 36 - B4B	

160 QC 21 - SA	200 pcs ✓	8/30/19	0.00 0.00	QC 21 - SA - 21 →	ST180
				QC 21 - SA - 70	21
				QC 21 - SA - 53	21

Part Op 100 - 1- TURN AS PER DWG 2- Deburr
 Descriptions: 115 - (QC2- Inspect parts off machine FAI/FAIB)
 120 - (QC8- Inspect parts - second check)
 130 - (Small Fab) CLEAN BUSHING BEFORE INSTALLING RUBBER. Insert rubber tubing in stainless steel bushing and cut rubber flush to the stainless bushing as per dwg.
 140 - (QC5- Inspect part completeness to step on W/O)
 150 - (Identify as per dwg & Stock Location: _____)
 160 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
M303R0.250	303 Round Bar 0.250"	6.6000 ft (.033 ea)	100-Hardinge - 1	S203771
D5649-1	Rubber Tube	6 ft (.03 ea)	130-Small Fab - 2 - B4B	S169950

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Hardinge - 1	M303R0.250	7	13	0
130-Small Fab - 2 - B4B	D5649-1	6	482	0

Part Specifications

Specifications could not be found.

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date : _____	Sequence #: _____	QTY Affected : _____		MRB (QSI042)	
Description Work Order Deviation		Disposition		Completed By	
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Presservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐ ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					